

Top Lifting Services Ltd

Unit 5A  
Europa Business Park  
Grimsby  
Lincolnshire  
DN31 2UJ  
Tel: 01472 357934

Hire, Sales & Service  
Test, Inspection & Repair Specialists

## Delivery Note

Account: sca002

SCAFFOLDING SUPPLIES LTD  
UNIT 3, MANBY ROAD  
IMMINGHAM  
N E LINCOLNSHIRE  
DN40 2LL

**Document No.** 1008153  
**Delivery Date** 02/12/2020  
**Their Ref.** OFFICE  
**Ordered By** JENNY  
**Order No.** G009004531

Item Number	Description	Quantity
	TEST TO DESTRUCTION ADJUSTABLE LEG	1.00

### Deliver To:

SCAFFOLDING SUPPLIES LTD  
UNIT 3, MANBY ROAD  
IMMINGHAM  
N E LINCOLNSHIRE  
DN40 2LL

**Signed:** \_\_\_\_\_

**Printed:** \_\_\_\_\_

**Date:** \_\_\_\_\_



See terms and conditions



**Report of a Load Test**

TOPLIFTING LIMITED  
UNIT D4, SOUTH ORBITAL TRADING PARK, HEDON ROAD,  
KINGSTON UPON HULL  
HU9 1NJ

Identification Number or Reference Number	Description of the Item to be Tested	Quantity to be Tested
BSL/11/19	ADJUSTABLE LEG	one

**Description of the Tests Applied**

The test was done on a hydraulic test rig using a hollow ram / pump and a calibrated pressure gauge.

**Results of the Test Identifying Any Defects**

The leg was subject to a force of 40kn and showed no patent defect. A force of 60kn was then applied and again no patent defect materialised.

The leg finally failed at a force of 100kn.  
The leg must be used at 0 degrees to the vertical.  
The adjuster must be set prior to the swl being applied – never adjusted under load where additional leverage or impact is needed.

I certify that the item/s described above have been tested in accordance with your instructions.

Authorised Signature.......... Date 02/12/2020.....

**Please Note: This report does not allow the above equipment to be put into service. An E. C. Declaration of Conformity or a LOLER Report of Thorough Examination may be required.**